



PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	HS99-1	Cap
2	1	HS99-2	Seal
3	1	HS99-3	O-Ring
4	1	HS99-4	Swivel Stem
5	3	HS99-5	Snap Ring
6	2	HS99-6	Bearing
7	1	HS99-7	Spacer
8	1	HS99-8	Swivel Body
9	1	HS99-9	Packing Seal
10	1	HS99-10	O-Ring
11	1	HS99-11	Rod Adaptor. Customer To Specify Thread Type.
12	1	HS99-12	Grease Zerk

THIS DRAWING CONTAINS PROPRIETARY INFORMATION AND SHALL NOT BE REPRODUCED, COPIED, OR USED AS A BASIS FOR ANY MANUFACTURING WITHOUT PERMISSION FROM NORTHWEST MACHINE WORKS . ALL DRAWINGS MUST BE RETURNED UPON REQUEST.

PROGRAM NO	REV	GENERAL SPECIFICATIONS UNLESS OTHERWISE SPECIFIED RADIUS ALL CORNERS .0313 ANGLES = +/-1° DEBURR ALL SHARP CORNERS				NO: _____ REVISIONS: _____ DATE: _____	DRAWN BY: Paul C	ISSUED 3-7-2012
							CHECKED BY:	DIScription: High Speed Water Swivel P & ID
							MATERIAL:	
							DWG NO. HSW-ASSY	

X	XX	XXX
.031	.01	.005
250 ✓	125 ✓	63 ✓

2318 GRAND PARK DR.
 GRAND JUNCTION, CO 81505
 970-242-1356