

.015625 --- 1/64	.359375 --- 23/64	.6875 ----- 11/16
.03125 ----- 1/32	.375 ----- 3/8	.703125 --- 45/64
.046875 --- 3/64	.390625 --- 25/64	.71875 ----- 23/32
.0625 ----- 1/16	.40625 ----- 13/32	.734375 --- 47/64
.078125 --- 5/64	.421875 --- 27/64	.75 ----- 3/4
.09375 ----- 3/32	.4375 ----- 7/16	.765625 --- 49/64
.109375 --- 7/64	.453125 --- 29/64	.78125 ----- 25/32
.125 ----- 1/8	.46875 ----- 15/32	.796875 --- 51/64
.140625 --- 9/64	.484375 --- 31/64	.8125 ----- 13/16
.15625 ----- 5/32	.5 ----- 1/2	.828125 --- 53/64
.171875 --- 11/64	.515625 --- 33/64	.84375 ----- 27/32
.1875 ----- 3/16	.53125 ----- 17/32	.859375 --- 55/64
.203125 --- 13/64	.546875 --- 35/64	.875 ----- 7/8
.21875 ----- 7/32	.5625 ----- 9/16	.890625 --- 57/64
.234375 --- 15/64	.578125 --- 37/64	.90625 ----- 29/32
.25 ----- 1/4	.59375 ----- 19/32	.921875 --- 59/64
.265625 --- 17/64	.609375 --- 39/64	.9375 ----- 15/16
.28125 ----- 9/32	.625 ----- 5/8	.953125 --- 61/64
.296875 --- 19/64	.640625 --- 41/64	.96875 ----- 31/32
.3125 ----- 5/16	.65625 ----- 21/32	.984375 --- 63/64
.328125 --- 21/64	.671875 --- 43/64	1. ----- 1.
.34375 ----- 11/32		

For reference purposes only. Northwest Machine Works, Inc. assumes no liability for errors associated with the use of these data.